



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
June 2, 2008

Supervisor LK

Mine Name: White Sands	Permit Number: S0210018
Operator Name: Silica Sand Company, Inc.	Inspection Date: 04/25/2008
Inspector(s): Tom Munson	Time: 1:00PM
Other Participants: none	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

Inspection Summary: The site has had very little work done on it recently. It was permitted in 1993 and therefore has had little or no work done on in 15 years. There is a small pathway or an old road to a white sand formation that has not been worked for quite a while. Some small metal pipes stuck in the ground and a cable attached to them that is partially buried were also visible. There is also some miscellaneous equipment that may or may not belong to the site. A claim paper was attached to a tree with Dennis Stowell name as claimant.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area. Write Mr. Stowell a letter asking him to reclaim the site or ask for an extension from the Board of Oil, Gas, and Mining.

Inspector's Signature

Thomas Munson

Tm:pb

cc: (OPERATOR)

ed_ginouves@blm.gov

O:\M021-Iron\S0210018-whitesands\inspections\insp-S210018-04252008.doc